

Рабочее давление P_н=1,0 Мпа	
d x G	L, мм
20 x 1/2"	76
20 x 3/4"	75
25 x 1/2"	81
25 x 3/4"	80
25 x 1"	80
32 x 3/4"	83
32 x 1"	83
32 x 1"1/4	81
40 x 1"	104
40 x 1"1/4	105
40 x 1"1/2	105
50 x 1"1/2	109
50 x 2"	109
63 x 1"1/2	128
63 x 2"	133
63 x 2"1/2	160
75 x 2"	173
75 x 2"1/2	174
75 x 3"	178
90 x 2"	205
90 x 2"1/2	203
90 x 3"	203
90 x 4"	203
110 x 4"	226